



PRODUCT CHANGE BULLETIN


 is an ISO 9001 Registered Manufacturer of Polyurethane Components for the Heavy-Duty Suspension Industry

LP50-24000 Bolster Spring (set of 2) Replaces HS10000 (set of 4)

Application: Hendrickson HN Series 402/460/462

Cross-reference:

Hendrickson	49377 49377000 60879000L
Arvin Meritor	R309410
Dayton Parts	334-852 334-852A
Euclid	E-11496 E-9410
Flagg	HS56
Gaff	13601



Quantity Per Vehicle: 2 kits (=4 pads)

Warranty: One year warranty when only bolster springs are installed.
Must replace bar pin end bushings, torque rod bushings and all bolster springs for three (3) year warranty on bolster springs.

If less than 4 bolster springs are installed at the same time, warranty is void.

ATRO Bolster Springs must never be used in conjunction with other bolster spring makes, doing so will void the warranty.

NOTE: Formerly ATRO part number HS10000 (set of 4)
HS10000 part number is discontinued IMMEDIATELY.

ATRO is not liable for any errors herein. All manufacturers' names and part numbers used are trademarked by the respective manufacturer. These names and part numbers are being used without permission. No endorsement, affiliation or recommendation is implied. They are included for reference purposes only. Some products shown here are covered by Canadian Patent 1,327,979; Australian Patent 630,358.



**PROUDLY MADE IN
SULLIVAN, MISSOURI ★ U.S.A.**

1250 Airport Road, Sullivan, Missouri 63080 USA
(573) 860-8400 • (800) 325-6114 toll-free • Fax: (573) 860-8401
www.atrobushing.com • e-mail sales@atrobushing.com

ATRO QUALITY... MOLDING THE FUTURE

©2010 ATRO ENGINEERED SYSTEMS, INC.

PA008-072810NPrevA