

ATRO

ENGINEERED SYSTEMS



HOOD LATCH CATALOG

WITH ATRO BEHIND YOU, DRIVE FORWARD.

6 Bolte Lane
St. Clair, Missouri 63077 | U.S.A.
800.325.6114 | Fax 866.920.2005
ATROBUSHING.COM

January 2021

BLUEBIRD

HL00-64006

Hood Latch Kit, Right Hand

Bluebird Vision School Bus

Replaces: 55554; 37-41-295-60

Length: 4-15/16" c-c

Contains:

(1) HL00-64005

(1) Catch Bracket, Right

Catch not sold separately



HL00-64007

Hood Latch Kit, Left Hand

Bluebird Vision School Bus

Replaces: 25159428

Length: 4-15/16" c-c

Contains:

(1) HL00-64005

(1) Catch Bracket, Left

Catch not sold separately



FREIGHTLINER

HL00-64001

Hood Latch

FL106, FL112, FL50, FL60, FL70, FL80 (1994-2005)

Replaces:

680880160

680-880-01-60

Length: 8-3/4"

Included in Kits: HL00-64003, HL00-64004



HL00-64002

Hood Latch Catch

M2 Business Class

Replaces:

17-14781-000

Length: 3-1/2"

Included in Kits:

HL00-64003, HL00-64004,

HL96-64018



HL46-64434

Hood Latch Catch

FLD/FLD Classic/XL

Replaces:

17-12434-000

Length: 5"

Included in Kits:

HL46-64480, HL46-64650, HL46-64651



HL46-64435

Hood Latch

FLD 120, 2003-09 Classic Offset Axle

Replaces:


17-12435-000

Length: 11-1/4"

Included in Kits:

HL46-64480, HL46-64530,

HL46-64531, HL46-64650, HL46-64651



HL46-64480

Hood Latch Kit

FLD 120, 2003-08 Classic Straight Axle

Replaces:

17-12348-000

17-12434-000 (catch)

17-12438-000 (no catch)

Length: 11-1/4"

Contains:

(1) HL46-64434

(1) HL46-64435



HL46-64530

Hood Latch Kit, Left Hand

Columbia (1995-2008)

Replaces:

A17-15553-000

Length: 11-1/4"

Contains:

(1) HL00-64002

(1) HL46-64435



HL46-64531

Hood Latch Kit, Right Hand

Columbia (1995-2008)

Replaces:

A17-15553-001

Length: 11-1/4"

Contains:

(1) HL00-64002

(1) HL46-64435



HL46-64650

Hood Latch Kit, Left Hand

FLD 120, Offset Axle

Replaces:

17-12434-000

17-12435-000

Length: 11-1/4"

Contains:

(1) HL46-64434

(1) HL46-64435



HL46-64651

Hood Latch Kit, Right Hand

FLD 120, Offset Axle

Replaces:

17-12434-001

17-12435-001

Length: 11-1/4"

Contains:

(1) HL46-64434

(1) HL46-64435



INTERNATIONAL

HL55-644C1

Hood Latch

3200: 41/42/43/4400

73/74/75/76/7700, 8500; Prosta

Replaces: 3544924C1

Length: 12-5/8"



HL55-64C91

Hood Latch Kit

1980-2011 Multi-Series

International 9200, 9300, 9400, 9900

Replaces: 1699930C91; 1699930C92;

1699930C93

Length: 6-7/8"



KENWORTH

HL00-64002

Hood Latch Catch

T300, T600, T800, W900

Replaces: L03-0001

Length: 3-1/2"

Included in Kits:

HL00-64003, HL00-64004, HL96-64018



HL00-64005

Hood Latch Assembly

T660

Replaces: 37-99-344

Length: 4-15/16" c-c

Included in Kits:

HL00-64006, HL00-64007



HL59-64033

Hood Latch Kit

T880 Vocational Truck

Replaces: L566033; L56-6033; L56-6048

Length: 5"



HL59-64107

Hood Latch

W900B, T600A (1987-2005);

T800 (1985-1987)

Replaces: K147C106; K147-107

Length: 5-1/2"



MACK

HL00-64005

Hood Latch Assembly

CH, CHN, CV, CXN

Replaces:

25159428

3QM313M

25169065

3QM313M2

Length: 4-15/16" c-c

Included in Kits:

HL00-64006, HL00-64007



HL00-64006

Hood Latch Kit, Right Hand

CH, CHN, CV, CXN

Replaces:

Latch Assy:

25169065

3QM313M2

Catch:

25165475

3QM314M

Length: 4-15/16" c-c

Contains:

(1) HL00-64005

(1) Catch Bracket, Right

Catch bracket not sold separately



HL00-64007

Hood Latch Kit, Left Hand

CH, CHN, CV, CXN

Replaces:

Latch Assy:

25159428

3QM313M

Catch:

25165476

3QM315M

Length: 4-15/16" c-c

Contains:

(1) HL00-64005

(1) Catch Bracket, Left

Catch bracket not sold separately



PACCAR

HL00-64003

Hood Latch Kit

T600A, T800, W900 (1987-96 & 2003-10)

Exc. Ball Style

Replaces:

63011005

63011005A

L56-0001

Length: 8-3/4"

Contains:


(1) HL00-64001

(1) HL00-64002

(1) Bracket

(1) Bolt

(1) Nut



HL00-64004

Hood Latch Kit

T600A, T800, W900 (1987-96 & 2003-10)

Exc. Ball Style

Replaces:

63011005

63011005A

L56-0001

Length: 8-3/4"

Contains:

(2) HL00-64001

(2) HL00-64002

(2) Bracket

(2) Bolt

(2) Nut



HL59-64027

Hood Latch

T680

Replaces:

L56-1042

L56-6027

Length:

3-1/8" c-c



**AVAILABLE
SUMMER 2021**

PETERBILT

HL00-64001

Hood Latch

357, 367, 377, 378,
379, 388, 389

Replaces:

1304339
161037
23-13857
L56-0001

Length: 8-3/4"

Included in Kits:

HL00-64003, HL00-64004



HL00-64002

Hood Latch Catch

379

Replaces:

L03-0001

Length: 3-1/2"

Included in Kits:

HL00-64003,
HL00-64004, HL96-64018



HL00-64003

Hood Latch Kit

T600A, T800, W900 (1987-96 & 2003-10)

Exc. Ball Style

Replaces:

23-13857
161037 (latch)

Length: 8-3/4"

Contains:

(1) HL00-64001
(1) HL00-64002
(1) Bracket
(1) Bolt
(1) Nut



HL00-64004

Hood Latch Kit

T600A, T800, W900 (1987-96 & 2003-10)

Exc. Ball Style

Replaces:

23-13857

Length: 8 3/4"

Contains:

(2) HL00-64001
(2) HL00-64002
(2) Bracket
(2) Bolt
(2) Nut



HL00-64005

Hood Latch Assembly

386

Replaces:

374129560

37-41-295-60

Length: 4-15/16" c-c

Included in Kits:

HL00-64006, HL00-64007



HL75-64372

Hood Latch Assembly

567 (2014 & newer)

Replaces:

37-99-372

Length: 4-15/16" c-c



VOLVO

HL00-64002

Hood Latch Catch

AC, WA, WC, WG, WI (1991-2002)

Replaces:

8174018 (kit)
671120003
671120004
671123801

Length: 3-1/2"

Included in Kits:

HL00-64003, HL00-64004, HL96-64018



HL96-64000

Hood Latch

AC, WA, WC, WG, WI (1991-2002)

Replaces:

671010002
671010005
671010006
671010007
671010008
8174018 (kit)

Length: 12-1/2"

Included in Kit:

HL96-64018



HL96-64018

Hood Latch Kit

AC, WA, WC, WG, WI (1991-2002)

Replaces:

1118205
8174018

Length: 12-1/2"

Contains:

(1) HL00-64002
(1) HL96-64000



Why ATRO Hood Latches?

The physical properties of ATRO's Polyurethane are so superior that rubber simply can't compete.

This is true for many truck components and applies to Hood Latches, in particular because:

- Hood Latches are exposed to the elements – Polyurethane is not affected by chemical attack
- The quality of rubber fluctuates – ATRO polyurethane is consistent.
- Repeated use causes rubber hood latch straps to break.
- ATRO Polyurethane has 3 X the tear strength of rubber.

©2021 ATRO LLC

ATRO Engineered Systems, Inc. is not liable for any errors herein. All manufacturers' names and part numbers are used without permission; no endorsement, affiliation, or recommendation is implied. They are included for reference purposes only.